




2.0 MACHINE TOOLS

2.1 Machining Lathe





2.1 Machining Lathe

MASCUT




C
E





2.1 Machining Lathe



Single Spindle Cam Type Automatic Lathe

Model	Number of Tool	Number of Tail-shaft	Max. Dia. of Processing (mm)	Max. Length of Processing for Tool No.1 (mm)	Max. Length of Processing for Tool No.5 (mm)	Max. Dia. of Drilling (mm)	Max. Dia. of Tapping (Free Cutting Steel)	Spindle Speed (r.p.m)	Conversion of Spindle Rotary Speed	Cam Shaft Speed (r.p.m)	Conversion of Cam Rotary Speed
JY-105	5	1	Ø 15	30	30	Ø8	M5	2150-5870	5	1.9-25.8	15
JY-1525			Ø 12 □ 10							2370-7400	
JY-2025		Ø 20 Ø 16 □ 14	35	30	Ø10	M10	1830-6400	1.1-28			
JY-32H		Ø 32 Ø 27 □ 22	75	50	Ø20	M20	50-3000	Variable Speed			
JY-42H		Ø 42 Ø 36 □ 28						Variable Speed		Variable Speed	